

CASE STUDY



Strain Gauging Services

COMPANY

BHP Hay Point Terminal Services

CHALLENGE

- Stacker conveyor fatigue risk assessment of increased payload
- Accurately measure and record strain and vibration for critical structural analysis purposes



OUTCOME

- Design audit
- Fulltime custom logging system deployment
- Custom database web reporting

